

Paulding Commercial Vehicles
4575 Atlanta Hwy
Hiram, GA 30141

ADDRESS

City of Powder Springs / David
Hicks

ESTIMATE 1017

DATE 10/20/2017

ACTIVITY	QTY	RATE	AMOUNT
Labor	15.50	105.00	1,627.50
Labor A/C Diagnostics	1	135.00	135.00
Parts Steer Gear Box	1	75.00	75.00
Parts Light for upper marker	1	20.00	20.00
Parts Gaskets	1	200.00	200.00
Parts Airline	1	100.00	100.00
Parts Gasket for the turbo	1	20.00	20.00
Parts Front Pinion seal	1	100.00	100.00
Parts Rear pinion seal	1	100.00	100.00
Parts shaft seal plus nut for the shaft seal	1	130.00	130.00

TOTAL

\$2,507.50

Accepted By

Accepted Date

ONDEMAND TRUCK SERVICE CENTER
 2301A BURNT WOOD DR
 KENNESAW GA 31052
 770-425-5382

10/16/2017 11:37 AM

page 1

Estimate #1833

CITY OF POWDER SPRINGS
 3006 SPRING INDUSTRIAL DR.
 POWDER SPRINGS GA 30127

Day Phone : 770.943.8010
 Eve Phone : 678.446.8188 Rick
 Cell Number 404.625.3643 David

Vehicle : 2006 Mack Granite CV713 12.0 L 728 CID L6
 VIN : 1M2AG11C96M038113
 Fleet # : SA02
 Created : 10/13/2017 9:42:47 AM

Last Mileage: 0
 Odometer In 0
 Odometer Out

Labor/Notes

Qty	Code/Tech*	Description	Unit Price	Price
1		REMOVE AND RESEAL TURBO RETURN	\$95.00	\$95.00
2.5		R&I FRONT PINION SEAL	\$95.00	\$237.50
2.5		R&I REAR PINION SEAL	\$95.00	\$237.50
2.5		R&I OUT PUT SHAFT SEAL	\$95.00	\$237.50
2		R&I RH STEERING GEAR BOX	\$95.00	\$190.00
0.5		R&I TOP R/H MARKER LIGHT	\$95.00	\$47.50
1		DIAG A/C	\$95.00	\$95.00
2		R&I LH STEERING GEAR BOX	\$95.00	\$190.00
		CONCERN, CAUSE, AND CORRECTION		

CUSTOMER STATES :

Parts

Qty	Code/Tech*	Description	Condition	Unit Price	Price
1		FRONT YOKE SEAL		\$28.72	\$28.72
1		THUSHAFT SEAL		\$27.96	\$27.96
1		FRONT PINION SEAL		\$27.44	\$27.44
1		TURBO OIL SEAL		\$15.06	\$15.06
1		LH GEAR BOX		\$867.28	\$867.28
1		CORE CHARGE		\$0.00	\$0.00
1		RH GEAR BOX		\$919.34	\$919.34
1		CORE CHARGE		\$0.00	\$0.00

Labor	\$1,330.00
Parts	\$1,885.80
Sublet/Misc.	\$0.00
Shop Supplies	\$30.00
Charges	\$0.00
Sales Tax	Tax @ \$1,885.80 * 6.0000% \$113.15
Estimate	\$3,358.95

This is an estimate for labor and material and could be subject to change. We look forward to working with you.

Estimates are valid for 30 days.

NEW ESTIMATE
PG 1

FLEET COPY: 5
POSTED: 10/09/17 04:10 pm EDT
ETR: 06/28/16 01:00 pm EDT

Nextran Corporation - Kennesaw (Mack)
1414 Shiloh Road Kennesaw, Georgia 30144
Phone: (770) 427-5230 - Fax: (770) 427-7737

ASIST

Case Number: 6863511 - Repair Order Number: ~~PW86092~~
Purchase Order Number: ~~10-03256~~
Service Writer: Service--, -Kennesaw - Case Date: ~~05/10/16 10:52 am EDT~~
10/9/2017

City Of Powder Springs	Unit #: SA-02		
Address: 3006 SPRINGS IND. DRIVE POWDER SPRINGS, GA 30127	Asset: 2006 Mack CV713	Miles: 104,790	
Phone: 943-8010	Serial #: 6M038113	Warranty Start: 3/2/2006	
Fax:	VIN: 1M2AG11C98M038113	In Service: 11 Years 7 Months	
Cust #: 83831	Engine: E7		
	Engine Hours: 13,542		



Item	Operation	Labor	Parts	Core Charge	Total
1	CSA Check 22 Inspection	\$0.00	\$0.00	\$0.00	\$0.00
2	Perform Preliminary Diagnostics Complaint: 1) OIL LEAK ON PASSENGER SIDE OF ENGINE. 2) DRIVER SIDE FRONT WHEEL AREA HAS AN AIR LEAK. 3) CHECK A/C FOR PROPER COOLING.	\$294.00	\$0.00	\$0.00	\$294.00
3	QM Miscellaneous (999) Parts: (1.0) GSKT TURBO OIL DRAIN, (1.0) O-RING TURBO DRAIN, (1.0) misc Complaint: TURBO RETURN TUBE IS LEAKING OIL. Cause: WORN SEALS Correction: REMOVE AND RESEAL TURBO RETURN TUBE.	\$15.29	\$11.36	\$0.00	\$26.65

New Estimate
PS-2

Dealer: Nextran Corporation - Kennesaw (Mack) - Version: 5 - Posted: 10/09/17 04:10 pm EDT - Fleet: City Of Powder Springs - Unit: SA-02 -
Asset: 2008 Mack CV713 - SN: 6M038113

4	<p>QM Pinion Seal Parts: (1.0) SEAL, DR. YOKE FRONT OIL 1513, (1.0) misc Complaint: FRONT PINION SEAL IS LEAKING. Cause: WORN BEYOND SERVICE Correction: REMOVE AND REPLACE FRONT PINION SEAL.</p>	\$279.30	\$13.14	\$0.00	\$292.44
5	<p>QM Pinion Seal Parts: (1.0) SEAL, FRONT DRIVE FLANGE (88AX457), (1.0) misc Complaint: REAR PINION SEAL IS LEAKING Cause: WORN BEYOND SERVICE. (NORMAL WEAR AND TARE) Correction: REMOVE AND REPLACE REAR PINION SEAL.</p>	\$279.39	\$12.88	\$0.00	\$292.27
6	<p>QM Pinion Seal Parts: (1.0) SEAL THRU SHAFT GRD92, (1.0) misc Complaint: FRONT DIFF. OUT PUT SHAFT SEAL IS LEAKING. Cause: WORN BEYOND SERVICE. (NORMAL WEAR AND TARE). Correction: REMOVE AND REPLACE FRONT DIFF. OUT PUT SHAFT SEAL.</p>	\$279.39	\$13.07	\$0.00	\$292.46
7	<p>QM Steering Gear (w/filter) Parts: (1.0) BOLT 5/8 X3-3/4"GR8F, (1.0) FILTER POWER STEERING, (1.0) LOCKNUT SC220/PI537, (1.0) SCREW MACH 1122, (1.0) STEER GEAR CV L/H 20QC545P2 M100PPJ(Core:450.00), (1.0) misc, (2.0) SCREWS, (3.0) WASHER 7/8" HARDENED, (4.0) MOBIL ATF D/M Complaint: STEERING GEAR BOX LEAKING. Cause: USAGE AND TIME. Correction: REMOVE AND REPLACE STEERING GEAR BOX AND FILTER, ADD POWER STEERING FLUID AS NEEDED, OPERATE STEERING SYSTEM WITH IN NORMAL OPERATING TEMPERATURES AND RE CHECK FOR ANY FURTHER LEAKAGE.</p>	\$1,028.60	\$2,140.64	\$450.00	\$3,619.24

New Estimate
Pg. 3

Dealer: Nextran Corporation - Kennesaw (Mack) - Version: 5 - Posted: 10/09/17 04:10 pm EDT - Fleet: City Of Powder Springs - Unit: SA-02 -
Asset: 2006 Mack CV719 - S/N: 6M038113

8	QM Electrical Systems (999) Parts: (1.0) LED MDL 10 M/C LAMP, BULK. (1.0) misc Complaint: UPPER R/H MARKER LIGHT IS INOP. (RED) Cause: BURNT OUT Correction: REMOVE AND REPLACE R/H UPPER MARKER LIGHT	\$44.10	\$6.80	\$0.00	\$50.90
9	QM A/C Compressor (Exac & Recharge + Dryer) Complaint: A/C IS NOT VERY COLD Correction: VAC SYSTEM DOWN, REPLACE DRYER AND RECHARGE. TEST SYSTEM AND VERIFY NO LEAKAGE.	\$556.00	\$0.00	\$0.00	\$556.00

Parts: \$2,197.89
Labor: \$2,776.07
Core: \$450.00
Haz. Waste: \$0.00
Shop: \$250.00
Freight: \$0.00
~~Tax: \$179.87~~
TOTAL: \$5,847.83

This estimate is subject to teardown and inspection and is valid for 30 days from date above. I, the undersigned, authorize you to perform the repairs and furnish the necessary materials. I understand any costs verbally quoted are an estimate only and not binding. Your employees may operate vehicle for inspecting, testing and delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. AUTHORIZED
BY: _____ DATE: ___/___/___