

FLEET COPY: 2
POSTED: 05/19/16 10:27 am EDT

Nextran Corporation - Kennesaw (Mack)

1414 Shiloh Road Kennesaw, Georgia 30144
Phone: (770) 427-5230 - Fax: (770) 427-7737Case Number: 6863511 - Repair Order Number: PW66092 - Purchase Order Number: n/a
Service Writer: Service--, --Kennesaw - Case Date: 05/19/16 10:27 am EDT

City Of Powder Springs

Unit #: SA-02

Address: 3006 SPRINGS IND. DRIVE

Asset: 2006 Mack CV713

Miles: 104,790

POWDER SPRINGS, GA 30127

Serial #: 6M038113

Warranty Start: 3/2/2006

Phone: 943-8010

VIN: 1M2AG11C96M038113

In Service: 10 Years 2 Months

Fax:

Engine: E7

Cust #: 83631

Engine Hours: 13642

Item	Operation	Labor	Parts	Cure Charge	Total
1	CSA Check 22 Inspection	\$0.00	\$0.00	\$0.00	\$0.00
2	Perform Preliminary Diagnostics Complaint: 1) OIL LEAK ON PASSENGER SIDE OF ENGINE. 2) DRIVER SIDE FRONT WHEEL AREA HAS AN AIR LEAK. 3) CHECK A/C FOR PROPER COOLING.	\$278.00	\$0.00	\$0.00	\$278.00
3	QM Miscellaneous (999) Parts: (1) GSKT TURBO OIL DRAIN, (1) O-RING TURBO DRAIN Complaint: TURBO RETURN TUBE IS LEAKING OIL. Cause: WORN SEALS Correction: REMOVE AND RESEAL TURBO RETURN TUBE.	\$13.90	\$10.24	\$0.00	\$24.14
4	QM Pinion Seal Parts: (1) SEAL, DR. YOKE FRONT OIL 1513 Complaint: FRONT PINION SEAL IS LEAKING. Cause: WORN BEYOND SERVICE Correction: REMOVE AND REPLACE FRONT PINION SEAL.	\$264.10	\$12.58	\$0.00	\$276.68
5	QM Pinion Seal Parts: (1) SEAL, FRONT DRIVE FLANGE (88AX457) Complaint: REAR PINION SEAL IS LEAKING	\$264.10	\$12.01	\$0.00	\$276.11

Dealer: Nextran Corporation - Kennesaw (Mack) - Version: 2 - Posted: 05/19/16 10:27 am EDT - Fleet: City Of Powder Springs - Unit: SA-02 -
Asset: 2006 Mack CV713 - S/N: 6M038113

	Cause: WORN BEYOND SERVICE. (NORMAL WEAR AND TARE) Correction: REMOVE AND REPLACE REAR PINION SEAL.				
6	QM Pinion Seal Parts: (1) SEAL THRUSHAFT CRD92 Complaint: FRONT DIFF. OUT PUT SHAFT SEAL IS LEAKING. Cause: WORN BEYOND SERVICE. (NORMAL WEAR AND TARE). Correction: REMOVE AND REPLACE FRONT DIFF. OUT PUT SHAFT SEAL.	\$264.10	\$12.24	\$0.00	\$276.34
7	QM Steering Gear (w/filter) Parts: (1) BOLT 5/8 X3-3/4"GR8F, (1) FILTER POWER STEERING, (1) LOCKNUT SC220/PI537, (1) SCREW MACH 1122, (1) STEER GEAR CV L/H 20QC545P2 M100PPJ(Core:450.00), (2) SCREWS, (3).WASHER 7/8" HARDENED, (4) MOBIL ATF D/M Complaint: STEERING GEAR BOX LEAKING. Cause: USAGE AND TIME. Correction: REMOVE AND REPLACE STEERING GEAR BOX AND FILTER, ADD POWER STEERING FLUID AS NEEDED. OPERATE STEERING SYSTEM WITH IN NORMAL OPERATING TEMPERATURES AND RE CHECK FOR ANY FURTHER LEAKAGE.	\$973.00	\$1,881.83	\$450.00	\$3,304.83
8	QM Electrical Systems (999) Parts: (1) LED MDL 10 M/C LAMP, BULK Complaint: UPPER R/H MARKER LIGHT IS INOP. (RED) Cause: BURNT OUT Correction: REMOVE AND REPLACE R/H UPPER MARKER LIGHT	\$20.85	\$6.19	\$0.00	\$27.04
9	QM A/C Compressor (Exac & Recharge + Dryer) Complaint: A/C IS NOT VERY COLD Correction: VAC SYSTEM DOWN,REPLACE DRYER AND RECHARGE . TEST SYSTEM AND VERIFY NO LEAKAGE.	\$556.00	\$0.00	\$0.00	\$556.00

Parts: \$1,935.09

Dealer: Nextran Corporation - Kennesaw (Mack) - Version: 2 - Posted: 05/19/16 10:27 am EDT - Fleet: City Of Powder Springs - Unit: SA-02 -
Asset: 2006 Mack CV713 - S/N: 6MD38113

Labor:	\$2,634.05
Core:	\$450.00
Haz. Waste:	\$0.00
Shop:	\$250.00
Freight:	\$0.00
Tax:	\$158.11
TOTAL:	\$5,427.25

This estimate is subject to teardown and inspection and is valid for 30 days from date above. I, the undersigned, authorize you to perform the repairs and furnish the necessary materials. I understand any costs verbally quoted are an estimate only and not binding. Your employees may operate vehicle for inspecting, testing and delivery at my risk. You will not be responsible for loss or damage to vehicle or articles left in it. AUTHORIZED

BY: _____ DATE: ____/____/____