

**REPORT OF REQUEST FOR QUOTES FOR INFRASTRUCTURE REPAIR WORK AT MULTIPLE LOCATIONS**

**PROJECT LOCATIONS - MACEDONIA ROAD, PEMBROOKE WAY, PINEGROVE DRIVE AND LEWIS-ATLANTA ROAD ROUNDABOUT**

<b>NAME OF CONTRACTOR</b>	<b>BID AMOUNT</b>	<b>REMARKS</b>
<b>ARDITO CONSTRUCTION</b>	<b>\$ 22,546.00</b>	
<b>INTERNATIONAL BUSINESS SOLUTIONS</b>	<b>\$ 15,960.00</b>	<b>RECOMMENDED FOR THE AWARD OF THIS WORK</b>
<b>TUCKER GRADING</b>		<b>NO RESPONSE</b>
<b>EAST COAST GRADING</b>		<b>NO RESPONSE</b>
<b>KENNEDY AND TILLMANCOMPNY</b>		<b>NO RESPONSE</b>



# Ardito Construction Company Inc.

1290 Austell Road, SE  
Marietta, GA 30008

**ARDITO**  
CONSTRUCTION COMPANY INC.  
7 CORPORATE BLVD. SUITE 1000 ATLANTA, GA 30328

Phone/ Fax: 770-435-3776

E-mail: chuck.ardito@arditoconstruction.com

# Estimate

Date	Estimate #
11/8/2018	541

Name / Address

City of Powder Springs  
3006 Springs Industrial Dr.  
Powder Springs, Ga. 30127

Project

Infrastructure Repair Work

Description	Qty	Unit	Unit Price	Total	
<b>NOTE:</b>					
1. Removal of Existing Sidewalk					
2. Concrete "Short Load" Fee					
3. Grading Complete					
- Sidewalk 4 inches Thick	120	S.F.	7.95	954.00	
- GDOT 1034D Double Wing Catch Basin Top	1	EA	2,800.00	2,800.00	
<b>PART II Total:</b>				<b>5,373.50</b>	
<b>PART III</b>					
Repair Part of Broken Concrete Median with Dowels					
Lewis Road/ Atlanta Street Roundabout					
- Median Repair (Approximately 16 S.F.)	1	L.S.	1,250.00	1,250.00	
<b>PART III Total:</b>				<b>1,250.00</b>	
Please Call Me If You Have Any Questions Or Concerns:(678) 618-0240				<b>Estimate Total:</b>	<b>\$22,546.05</b>



# Ardito Construction Company Inc.

1290 Austell Road, SE  
Marietta, GA 30008

**ARDITO**  
CONSTRUCTION COMPANY INC.  
INCORPORATED IN GEORGIA

Phone/ Fax: 770-435-3776  
E-mail: chuck.ardito@arditoconstruction.com

# Estimate

Date	Estimate #
11/8/2018	541

Name / Address

City of Powder Springs  
3006 Springs Industrial Dr.  
Powder Springs, Ga. 30127

Project

Infrastructure Repair Work

Description	Qty	Unit	Unit Price	Total
Infrastructure Repair Work				
<b>PART I</b>				
Remove and Replace Existing Sidewalk Near Address Shown				
3771 Macedonia Road				
3711 Macedonia Road				
3681 Macedonia Road				
3691 Macedonia Road				
Pine Grove Drive				
4440 Pembroke Way				
- Asphalt/ Concrete Saw Cut	60	L.F.	2.00	120.00
- Haul Off (Concrete)	13	C.Y.	25.00	325.00
- Traffic Control	12	EA	250.00	3,000.00
- Contractor's Hourly Rate	18	Hrs.	250.00	4,500.00
NOTE:				
1. Removal of Existing Sidewalk				
2. Concrete "Short Load" Fee				
3. Grading Complete				
- Sidewalk 4 inches Thick	689	S.F.	7.95	5,477.55
- Clearing and Grubbing/ Tree & Stump Removal at 3711 Macedonia Road	1	EA	2,500.00	2,500.00
<b>PART I Total:</b>				15,922.55
<b>PART II</b>				
Remove and Replace Reinforced Concrete Catch Basin Top and Sidewalk				
3900 Macedonia Road (Tapp Middle School)				
- Asphalt/ Concrete Saw Cut	16	L.F.	2.00	32.00
- Haul Off (Concrete)	3.5	C.Y.	25.00	87.50
- Traffic Control	2	EA	250.00	500.00
- Contractor's Hourly Rate	4	Hrs.	250.00	1,000.00
Please Call Me If You Have Any Questions Or Concerns:(678) 618-0240				<b>Estimate Total:</b>

# IBSG

## International Business Solutions (IBS) Groups LLC

1145 Montclair Way  
Snellville, GA 30078

November 7th, 2018

### **RE: Storm water infrastructure repair works**

Dear Mr. Michael Asiedu,

As per your email of October 18<sup>th</sup>, 2018, our lump sum Quotation for the entire project is **\$15,960**. The quote is based on the following work order stipulated in the Request for Quotation:

#### PART I

Remove and replace existing sidewalk near address as shown:

3771 Macedonia Road

- (+/-23 feet x width of existing sidewalk)

3711 Macedonia Road

- (+/-28 feet x width of existing sidewalk)
- (+/-10 feet x width of existing sidewalk)

3681 Macedonia Road

- (+/-15 feet x width of existing sidewalk)

3691 Macedonia Road

- (+/-25 feet x width of existing sidewalk)

Pinegrove Drive (marked)

- (+/-35 feet x width of existing sidewalk)

4440 Pembroke Way

- (+/-25 feet x width of existing sidewalk)

#### PART II

Remove and replace reinforced concrete catch basin top and sidewalk:

3900 Macedonia Road (TAPP Middle School)

- +/-30 feet x width of existing sidewalk
- Double wing catch basin top
- Allow for extra grading and grassing (40 feet x 10 feet)

#### PART III

Repair part of broken concrete median with dowels

Lewis Road/Atlanta Street roundabout

# IBSG


---

## International Business Solutions (IBS) Groups LLC

The quote includes all traffic controls, BMPs and restoration activities. It is also based on the work being done to the standards listed in the RFQ.

Please let me know of any additional information you may need. You may email me or contact me at 404-642-1252.

Sincerely



Robert A. Baffour, PhD  
President/CEO